

FIRST RE-ESTABLISHMENT

GCDB 500140

Quarter corner common to Sections 34 and 35 of Township 36 South, Range 3 East, W.M.

Found at corner position exp. 8 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966 and marked:

T36SR3E
¼
S34 | S35
1966

Single remaining original bearing tree recorded by Rufus S. Moore of the G.L.O. in 1883 found with healed double blaze and measured to center at base, a P.Pine now 32 ins. brs. S32°E, 44.3 ft., record S33°E, 44.9 ft.

Bearing trees recorded by the B.L.M. in 1966 found with a healed single blazes and measured to center at base,

- Cedar now 16 ins. diam. brs. record; N83°E, 9.2 ft.
- D.fir now 15 ins. diam. brs. S62°W, 25.4 ft., record 25.1 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- Cedar 16 ins. diam. brs, N32½°W, 34.0 ft.

Corner lies approx. 800 ft. N30° E, of intersection of dirt logging roads.

February 4, 2009

B. Beeman
H.Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 27
V. – 18°