

FIRST RE-ESTABLISHMENT

GCDB 500400

Section corner common to Sections 14, 15, 22, and 23 of Township 36 South, Range 3 East, W.M. Found at the corner position, exposed 6 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962 and marked:

T36SR3E
S15 | S14
—+—
S22 | S23
1962

Single remaining original bearing tree recorded by Rufus Moore of the GLO in 1883 found with a healed blaze and measured to center at base;

- D. fir dead, down, and rotted brs. record; S31°E, 11.2 ft.

Bearing trees recorded by the BLM in 1962 found with healed single blazes and measured to center at base;

- D. fir now 19 ins. diam. brs. S37°E, 29.7 ft. record ; S36°E
- D. fir now 15 ins. diam. brs. S78°W, 14.5 ft. record ; S79°W
- D. fir now 29 ins. diam. brs. record; S5°W, 35.0 ft.

Marked a new bearing tree 'CS''BT' and measured to center at lower blaze;

- Madrone 8 ins. diam. brs. N41°E, 13.9 ft.

Corner lies approx. 450 ft east of gravel road on blazed/posted line.

December 21, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. -275

V. - 15°25'