

FIRST RE-ESTABLISHMENT

GCDB 540400

Quarter corner common to Sections 14 and 23, Township 36 South, Range 3 East, W.M. $V = 18\frac{3}{4}^\circ$

Found original N.E. BT, now an irregularly shaped Douglas Fir, 24 ins. diam., with healed lower blaze and scribed " $\frac{1}{4}$ S" visible in partially opened upper face.

From which evidence and at record bearing and distance, I set a 1 in. x 36 ins. G.I. pipe, 12 ins. in sandstone strata, with a $2\frac{1}{2}$ ins. bronze disc marked:

T36S R3E
14
 $\frac{1}{4}$ S —
23
C.S.
1973

The immediate area has been disturbed by a tractor and the original basalt stone (24 x 12 x 12 ins.), marked " $\frac{1}{4}$ " by R. Moore in 1883 was found about 30 feet downhill from re-established corner location. Said stone deposited alongside corner as memorial.

I marked new trees, C.S. BT:

- A Douglas Fir, 14 ins. diam., bears $S20^\circ W$, 53.4 feet to center of tree at lower blaze.
- A Douglas Fir, 18 ins. diam., bears $N26^\circ W$, 76.7 feet to center of tree at lower blaze.

Location marker place on road approximately 1,200 feet W. of corner.

August 15, 1973
E. Graham
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor