

FIRST RE-ESTABLISHMENT

ANGLE POINT

GCDB 647700

Angle Point on the line between Sec. 1, Township 36 South, Range 3 East, and Sec. 36, Township 35 South, Range 3 East, W.M. $V = 22^\circ$

Said point being identical to that point established by R. Moore in 1883 as the South $\frac{1}{4}$ corner of Section 36, T35S, R3E. This point was visited by Lincoln Wilkes in 1925, at which time he constructed a mound of stone and marked two new trees.

Fd. the stone set by R. Moore, 18 x 12 x 10 ins. with $\frac{1}{4}$ SC marked on the North face, firmly set projecting 7 ins. in a ring of stone. A mound of stone 3 x 4 x 3 ft. high bears North, 3 ft. I replace said stone with a 1 x 36 ins. G. I. pipe set 24 ins. in the ground with a 2 $\frac{1}{2}$ ins. bronze disc mkd.:

Jackson County
T35S R3E
36
*
1
T36S
1975

From which

- The D. Fir marked by Wilkes, now 23 ins. diam., with healed blazes, bears record N47°E, 67.32 ft. to center.
- The dead and down remains of a Fir, marked by Wilkes, now 9 ins. diam. scribed SC $\frac{1}{4}$ in open upper face, fd. the stump of which bears record N6°W, 8.58 ft.
- Madrone remains fd. at record location of Moore's N.W.B.T.

I mound stones around corner, deposit original stone alongside as a memorial and mark a new tree C.S.B.T.:

- A D. Fir, 16 ins. diam., bears N 86 $\frac{1}{2}$ ° E, 13.9 ft. to center of tree at lower blaze.

Nov. 25, 1975

R. Frost

B. Malotte

K. Weaver

Approved by: Ed McGinty
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

ANGLE POINT

GCDB 647700

Angle point common to Section 36, Township 35 South, and Section 1, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1977, marked:

T35S R3E
S36
AP —
S1
T36S
1977

Single remaining original bearing tree recorded by L. Wilkes of the GLO in 1925

- A D. Fir now 28 ins. diam. with healed blazes, brs. record; N44°E, 67.3 ft. to center at base.

Bearing tree recorded on 1st Re-establishment in 1975, found with healed double blazes and measured to center at lower blaze:

- D. Fir now 18 ins. diam. brs. record; N82°E, 13.2 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- D. Fir 9 ins. diam. brs. S41°E, 2.5 ft.

Corner lies approx. 2000 ft. east of gate at cinder pit.

December 20, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 102

V. – 15°15'