

FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 36 ONLY
GCDB 700140

East Quarter corner of Section 36 only, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 4 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T36S
R3E
¼ S36 |
1966

Original bearing trees recorded by L. E. Wilkes of the GLO in 1923, found with healed blazes and measured to center at base:

- Sawed Fir stump 33 ins. diam. brs. record; N41°W, 21.8 ft.
- W. Fir 16 ins. diam. brs. record; S54°W, 2.6 ft.

Bearing tree recorded by the BLM in 1966, found and measured to center of tree at base:

- Cedar snag 14 ins. diam. with scribe marks "¼ S36 BT" in partially healed single blazes brs. record; S26°W, 36.3 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- W. Fir 7 ins. diam. brs. S14½°W, 35.2 ft.

The 1923 GLO monument for the west quarter corner of Section 31 only, Township 36 South, Range 4 East, brs. N1¼°E, 24.8 ft.

Corner is located approx. S 70° E, 600 ft. from end of logging spur road.

January 31, 2012
H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 126
V. – 15°15'