

**FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 13 ONLY
GCDB 700440**

East quarter corner to Section 13 only, Township 36 South, Range 3 East, W.M. $V = 19\frac{1}{4}^\circ$

Corner lies in the 15 feet diam. root hole of a down Fir, 40 ins. diam., the original (West) bearing tree recorded by R. Moore in 1883.

The BLM (1962) pipe and brass cap was found distant, having apparently been displaced by the tipped over tree.

I re-set the above $2\frac{1}{2}$ ins. pipe, now projects 8 ins., with brass cap marked as recorded:

T36S
R3E
 $\frac{1}{4}$ S13 |
1962

From which:

A sawed Fir stump, 24 ins. diam. found at record location of L. Wilkes (1925) Southeast BT. Bearing trees marked by BLM in 1962 found as follows:

- White Fir, 12 ins. diam. with healed blazes, bears Record: $S19^\circ W$, 58.74 feet to center.
- Fir snag, 13 ins. diam., with all scribes visible, bears $N38^\circ W$, 31.02 feet to center. Record: $N37^\circ W$, 31.02 feet.

I deposit found 16 x 14 x 6 ins. stone, marked as recorded by L. Wilkes alongside corner and mk. a new tree CS BT:

- Yew, 13 ins. diam. bears $N12\frac{1}{2}^\circ E$, 24.6 feet to center of tree at lower blaze.

Note: no available tree in West quadrants.

The brass cap $\frac{1}{4}$ corner of Sections 18, bears $S\frac{1}{2}^\circ W$, 40.63 feet.

December 14, 1978
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor