

FIRST RE-ESTABLISHMENT

CORNER COMMON TO SECTIONS 1 AND 6 ONLY

GCDB 700700

Closing corner common to Section 1, Township 36 South, Range 3 East, and Section 6, Township 36 South, Range 4 East, W.M. $V = 21^\circ$

Found the 3 ins. diam., G.I. pipe with the bronze disc attached as set by Lincoln Wilkes in 1925. The pipe is exposed 6 ins. and the B.C. is marked:

T35S R3E	
S36	

S1	S6
R3E	R4E
T36S	
1925	

From which a Douglas Fir 26 ins. diam. with healed blazes bears record, S14°W, 39.6 feet to estimated face of blaze.

- A sawed Douglas Fir stump, 24 ins. diam., with the lower blaze healed, bears S10°E, 58.0 feet to estimated face of blaze (record, S9½°E, 57.75 feet.)
- The original closing corner as set by R. Moore in 1883, a stone 18 x 12 x 6 ins. with visible grooves found in a mound of stone, bears S1°E, 18.0 feet. (Record, S0°50'W, 18.48 feet.)

I marked new trees C.S. BT and take measurements to the center of tree at lower blaze:

- W. Fir, 5 ins. diam., bears S18°E, 18.7 feet.
- W. Fir, 8 ins. diam., bears S65°E, 34.3 feet.
- Centerline of a logging road bears S65°E, 45 feet.

November 19, 1975
B. Malotte
K. Weaver

Approved by: Edward McGinty
County Surveyor