

FIRST RE-ESTABLISHMENT

GCDB 100400

Section corner common to Sections 18 and 19, Township 36 South, Range 4 West and Sections 13 and 24, Township 36 South, Range 5 West. W.M.

At the corner of Sections 18, 19, 13, 24, Twp. 36 S., Range 4 & 5, I found a 2 inch iron pipe in mound of rock protruding 1½ feet above ground from which:

- A dead and down Yellow Pine, 18 inches in diam. bears N68°E., 72 lks, dist., scribe visible.
- A yellow pine 12 inches in diam., bears S. 48½° W., 80 lks. dist., scribe visible, blaze partially healed, (record, 18 inch Yellow Pine).
- A white Oak 10 inches diam., bears N. 46½° W., 80 lks. dist., blaze healed, scribe visible.

In the found 2 inch iron pipe I set a Brass Cap marked:

		T36S		
R5W	13		18	R4W
	24		19	
				1973

From which a new bearing tree:

- A White Oak 8 ins. diam. bears N. 42° E., 37.1 feet dist. marked "CS S18 BT".

November 29, 1973
R. L. Templin, R.E. 3024
Witnesses: M. Ager
W. Edwards
Josephine County Surveyor

ALSO SEE RECORDED SURVEY NO. 1327