

## FIRST RE-ESTABLISHMENT

GCDB 200540

Quarter corner common to Sections 7 and 8, Township 36 South, Range 4 West, W.M.

Found projecting 8 ins. from ring of stone, the 1¼ ins. diam. iron pipe, reset on Survey No. 2315 in 1963. In the top of found pipe, in cement, set a 2½ ins. diam. brass cap marked:

T36S R4W  
¼ S  
7 | 8  
C.S.  
1987

An original bearing tree recorded by C. J. Howard in 1883, now a sawed fir stump, 38 ins. diam., containing scribed "BT", brs. N40°E, 13.2 feet to scribed face. Record 13.1 feet.

Bearing trees marked in 1961, on Survey No. 1834 and subsequently corrected on Survey No. 2315, in 1963 found:

- Fir snag, 14 ins. diam., scribed "¼S8RS404BT" in exposed single blaze, brs. S36°E, 56.0 feet to center of snag. Record; S35°E, 55.77 feet.
- Douglas Fir, 46 ins. diam., scribed "¼S7R404BT" in exposed single face, brs. N84°W, 20.0 feet to center of tree. Record; N83°W, 24.42 feet.

Mk a new tree "CS" "BT":

- Douglas fir, 6 ins. diam., brs. N38°E, 17.40 feet to center of tree at lower blaze.

Corner lies on North-East slope.

January 28, 1987  
R. Frost  
T. Newcomb

Edward McGinty  
County Surveyor

V = 20°  
P. -22