

FIRST RE-ESTABLISHMENT

GCDB 400540

Quarter Section Corner 9 and 10, Township 36 South, Range 4 West, W.M.

Found original Black Oak BT to N.E. with old blaze visible; from which evidence set a 1¼" x 26" iron pipe for corner;

From which,

- A 10" White Oak, scribed C.S.-BT, bears N59½°E, 131.0 feet.
- Scribe a 10" White Oak, C.S.-BT, which bears S39°E, 146.3 feet.

November 5, 1936
C. Z. Boyden, Deputy County Surveyor
C. I. Bourne, Chainman
D. J. Clifford, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 400540

Quarter corner common to Sections 9 and 10, Township 36 South, Range 4 West.

The 1¼" iron pipe and the Southeast bearing tree marked on the First re-establishment by Deputy County Surveyor C. Z. Boyden on November 5, 1936 have been destroyed. The corner location falls in Evans Creek.

I therefore compute the true corner location from the Northeast bearing tree marked on said first re-establishment (now a 13" White Oak with "CS" scribe in the upper blaze and the lower blaze left intact) and set a witness corner 100.84 feet due East from the true corner.

For witness corner, set a 1"x36" galvanized iron pipe, 34" in the ground with a 2½" bronze cap stamped:

T. 36 S. R. 4 W.
Witness
Corner
C.S.
1969

From said pipe witness corner, I mark the following new bearing trees:

- A 26" Yellow Pine, scribed "CS-BT" bears N9°08'E, 19.1 feet to the face of the lower blaze;
- A 17" Yellow Pine, scribed "CS-BT" bears N86°18'E, 42.8 feet to the face of the upper blaze.

October 1, 1969
F. Roberts, Deputy County Surveyor
O. Blankenship