

FIRST RE-ESTABLISHMENT

GCDB 400600

Corner common to Sections 3, 4, 9 and 10, Township 36 South, Range 4 West.

Found a 1¼" pipe with ½" pipe inside for corner. The 1¼" pipe is reported in notes of Evans Creek Road survey of 1938. Also found three original bearing trees.

Replaced the 1¼" pipe with a 1"x36" galvanized iron pipe set 33" in the ground with a 2½" bronze cap stamped:

T36S R4W	
Section Cor.	
4	3
----- c.s.	
9	10
1965	

From which:

- The original bearing tree (now a 28" White Oak with decayed face exposed - F.A. Roberts reported opening this tree in 1960 and found scribe), bears South 55° West, 19.8 feet;
- The original bearing tree (now a 26" White Oak with old scars) bears North 86° West, 34.6 feet to face of tree;
- The original bearing tree (now a 36" White Oak with old scars) bears South 23½° East, 26.9 feet to face of tree.

From said pipe corner, I establish a new witness tree:

- A 36" White Oak (not scribed) bears North 34½° East, 114.2 feet to the face of the tree.

November 23, 1965
L. D. Pinkham, Deputy County Surveyor
L. W. Hart