

FIRST RE-ESTABLISHMENT

GCDB 400640

Quarter Corner between Sections 3 and 4, Township 36 South, Range 4 West, W.M.

Found original bearing tree to the Northwest with scribe legible (tree was dead), found the stump of the original bearing tree to the Southeast with BT scribe legible,

From said evidence set:

1" x 36" galvanized iron pipe 34" in the ground for the corner, from which the following bearing trees scribed CS-BT:

- A 4" Laurel bears N45°00'W, 79.0 feet.
- A 14" White Oak bears S51°30'E, 240.4 feet.

November 23, 1936

C. Z. Boyden, Deputy County Surveyor

C. Bourne

D. Clifford

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 400640

Quarter corner common to Sections 3 and 4, Township 36 South, Range 4 West, W.M.

Found 1" galvanized iron pipe 3" deep set for corner on first re-establishment by Deputy County Surveyor C. Z. Boyden on November 23, 1936.

Replaced said 1" pipe corner monument with a 1"x36" galvanized iron pipe set 33" in the ground with 2½" bronze cap stamped:

T36S, R4W
¼ 4 | 3 cor.
C.S.
1972

From which:

- The Southeast bearing tree established on said first re-establishment bears S 50° 18' E, 241.0 feet to the center. (First re-establishment - 14" White Oak S51° 30' E, 240.4 feet).
- Scribed a 6" Black Oak "CS-BT" which bears N 46° 44' E, 42.4 feet to the face of the lower blaze.

June 7, 1972
G. Kaiser, Deputy County Surveyor
R. Webber

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 400640

Quarter corner common to Sections 3 and 4, Township 36 South, Range 4 West, W.M.

At the corner, found flush, the 1 ins. diam. iron pipe with 2½ ins. diam. brass cap marked:

T36S R4W
¼ 4 | 3
C.S.
1972

As recorded on Second re-establishment, page 32 in 1972.

Bearing trees noted on Second re-establishment found:

- Black Oak, 16 ins. diam. with healed blazes, brs. N46°44'E, 42.78 feet to center. Record: 42.4 feet.
- White Oak, sawed stump, brs. S50°18'E, distance not re-measured. Record: 241.0 feet.

Corner lies at the intersection of North-South and East-West fence line.

December 27, 1982
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 18°
P. -172