

## FIRST RE-ESTABLISHMENT

GCDB 540400

Quarter corner common to Sections 14 and 23, Township 36 South, Range 4 West, W.M.

At the corner, found projecting 5 ins., the 1 in. diam. iron pipe set on Survey No. 2192 in 1963. In the top of said pipe in cement, set a 2½ ins. diam. brass cap marked:

T36S R4W  
14  
¼S —  
23  
C.S.  
1981

A bearing tree marked on above noted survey,

- A Ponderosa Pine, 16 ins. diam. containing scribe marks in partly exposed face, burned by recent forest fire, brs. S51°E, 14.40 feet to center of tree. Record: 14.00 feet.

Remains of original bearing trees recorded by Ives & Hyde in 1854 found:

- The stump hole of down and burned Oak, about 12 ins. diam., brs. Record: S26°W, 62.7 feet.
- Burned Oak, partial stump shell, brs. Record: N66°W, 5.67 feet.

Set new references, 5/8 x 30 ins. rebars with yellow plastic caps marked "JACKSON C.S." as follows:

- S26°W, 61.78 feet projects 5 ins.
- N64°W, 5.67 feet projects 4 ins.

Marked a new tree "CS" "BT":

- Laurel, 20 ins. diam., brs. North, 66.1 feet to center of tree at lower blaze.

Corner lies 2 feet East of aluminum post.

November 9, 1981  
E. McGinty  
R. Frost

Edward McGinty  
County Surveyor

V = 19°

P. -185