

FIRST RE-ESTABLISHMENT

GCDB 540500

Quarter corner common to Sections 11 and 14, Township 36 South, Range 4 West, W.M.

- Original bearing tree in Section 14, intact but dead.
- Bearing tree in Section 11 destroyed.

Set at one 6x8x12" from which

- A new bearing tree, an 18" yellow pine bears N41°E., 7.09 feet.

A. T. Brown, County Surveyor
H.G. Diess, Chainman
May 11, 1917

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 540500

Quarter corner common to Sections 11 and 14, Township 36 South, Range 4 West, W.M.

Found projecting 3 ins., the $\frac{3}{4}$ ins. diam. iron pipe, set on Survey No. 2192, dated 1963, alongside of a 6x10x15 ins. unmarked stone.

Replace found pipe with and deposit it alongside a 1x36 ins. galvanized iron pipe, set 34 ins. in the ground with a 2 $\frac{1}{2}$ ins. diam. brass cap marked:

T36S R4W
11
 $\frac{1}{4}$ S —
14
C.S.
1987

A bearing tree recorded on first re-establishment, page 2, in 1917, and reported on the above noted survey, now a pine stub, 16 ins. diam., and partially burned (no scribing found), brs. N41°E, 7.90 feet to center of tree. Record: 7.09 feet.

Bearing trees marked on Survey No. 2192 found:

- The west branch, 12 ins. diam. of a double Madrone, with scribe marks visible in nearly healed upper face, brs. N44°E, 14.20 feet. to center of branch at lower blaze. Record: 14.0 feet.
- White Oak, 8 ins. diam., with healed blazes, brs. Record: S82°W, 34.6 feet to center of tree at lower blaze.

Corner lies on steep (50%) southerly slope, about 125 feet S82°W of location marker on 8 ins. diam. Madrone located atop main ridge c. N45°W and S20°E.

August 12, 1987
R. Frost, Tech III
S. Beecher, Tech I

Edward McGinty
County Surveyor

V = 20°
P. -294