

FIRST RE-ESTABLISHMENT

GCDB 600140

Quarter corner common to Sections 35 and 36, Township 36 South, Range 4 West.

Found

- Original bearing tree to Southwest with part of old scribe visible,
- Also original bearing tree to Northeast lying down with scribe visible;

From which

- Set a ½" x 18" iron pipe for corner,

From which:

- A 12" White Oak scribed CS-BT bears South $72\frac{3}{4}^{\circ}$ West, 50.5 feet;
- Scribed a 6" Forked White Oak CS-BT which bears North $69\frac{3}{4}^{\circ}$ East, 26.9 feet.

December 23, 1943

C. Z. Boyden

J. H. Cushman

D. L. Biles

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 600140

Quarter corner common to Sections 35 and 36, T. 36 S. R. 4 W. W.M.

Found the ½" iron pipe, exposed 3" as set for corner by Deputy County Surveyor, C. Z. Boyden on December 23, 1943.

Set a 1"x36" galvanized iron pipe over said ½" pipe, 34" in the ground with a 2½" bronze cap stamped:

T36S R4W
¼ 35 | 36 Cor.
C. S.
1971

From which:

- The original bearing tree (now a 12" Black oak with "¼S" scribe marks in relief) bears S46¾°W, 16.6 feet to the face of the upper blaze;
- The First Re-establishment bearing tree (now a 14" White Oak with healed blazes) bears S72½°W, 51.1 feet to the center of the tree;
- The First Re-establishment bearing tree (now a 9" White Oak with healed blazes) bears N69°E, 27.0 feet to the center of the northerly fork.

November 12, 1971
Gary Kaiser, Deputy County Surveyor
Lloyd Shreeve