


FIRST RE-ESTABLISHMENT                      SPECIAL CORNER  
DLC37SE  
GCDB 937050

Southeast corner to Donation Land Claim No. 37, located in Section 35, Township 36 South, Range 4 West, W.M.

Found flush, the 2 ins. diam. galvanized iron pipe, as set on Survey No. 2159 in 1963. To perpetuate this position, set a 2½ ins. brass cap in cement, in top of said pipe, marked:



Near the middle of a foot trail.

References set on the above noted survey; 5/8 ins. smooth iron pins, found flush, brs.:

- East (basis of bearing) 68.92 feet. Record: 70.00 feet.
- S89°59'46"W, 150.07 feet. Record: West, 150.00 feet.

A witness tree reported in 1963, now a sawed pine stump, 26 ins. diam. with "BT" tag alongside, brs. N50°05'14"W, 125.23 feet. Record: N45¼°W, 135.6 feet.

The southeast bearing tree, now a pine stump, is not visible from the corner due to black berry brush.

Take new references; 5/8 x 24 ins. rebars, flush, with Jackson County metal caps, br.:

- East, 18.93 feet, and
- S89°46'57"W, 25.78 feet.

Corner lies behind residence No. 396 Footh Creek Road and an estimated 25 feet northwest of a small pond.

November 27, 1995  
R. Frost, Tech.  
T. Newcomb

Roger Roberts  
County Surveyor

P. -68