

FIRST RE-ESTABLISHMENT

DLC39IL

GCDB 400334

Corner DLC #39 (Inside Ell)

On the West boundary of said claim, which corner is described in the official Government records as being 6.58 chains South of the $\frac{1}{4}$ Section corner to Sections 21 and 22, said Twp. and Range; found original BT to SW intact and plainly scribed; also stump at original BT to SE, no scribe visible.

No evidence of BT to NW;

From which evidence set a 7"x8"x5" stone with "X" thereon, 20" below surface of ground for corner;

From which:

- The original BT, a 28" Black Oak bears S. 61° W., 256.3 feet.
- Scribe a 10" Black Oak, C.S.-BT, which bears N. $88\frac{1}{2}^{\circ}$ W., 192.0 feet.

Note. No attempt made to locate this corner on the Section line.

August 6, 1936
C. Z. Boyden, Deputy County Surveyor
D. Clifford, Chainman
Fred Younger, Chainman

SECOND RE-ESTABLISHMENT

DLC39IL

GCDB 400334

Inside "ELL" corner to Donation Land Claim No. 39, Township 36 South, Range 4 West, W.M.

At the corner, found 6 ins. deep, the stone, marked with an "X" set on First re-establishment, page 7, dated 1936. Directly over the cross on said stone, level with the surface of the ground, in concrete, set a 2½ ins. diam. brass cap marked:

T36S R4W
DLC
— 39
ELL
C.S.
1982

From which,

- The single remaining original bearing tree, recorded by S. Truax in 1856 and noted on First re-establishment, now a partly hollow Black Oak stump, 33 ins. diam. with healed over outline of axed out face, brs. S61°13'W, 253.6 feet to center. Record: S61°W, 254.1 feet.

Take new references:

- Rebar, 5/8 x 30 ins., set 28 ins. in the ground with yellow plastic cap, marked "Jackson C.S.", located 1 foot Westerly of fence line c.N30°W, brs. S26°36'E, 35.13 feet.
- Ash, 17 ins. diam. (not scribed) brs. S14°36'W, 143.10 feet to center.
- Black Oak, 17 ins. diam., marked "CS" "BT", located about 20 feet east of irrigation canal, brs. S72°36'W, 192.00 feet to center.
- Rebar, 5/8 x 30 ins., set 28 ins. in the ground with yellow plastic cap marked "Jackson C.S.", located about 8 feet east of the Northeast corner of wood frame shed, brs. N74°15'W, 214.48 feet.
- A ½ ins. diam. iron pin, found 2 ins. deep, located approximately 12 feet North of the center of Lost Lane Road and about 57 feet S60°W of power pole No. R4491 brs. N1°06'30"W, 285.55 feet.

Corner lies 436.97 feet, S0°17'54"W of the brass cap (proportion) corner of Sections 21 & 22. See Special Corner Book. No attempt was made to determine the relationship between this corner and the section line common to Sections 21 & 22. See Survey No. 1473, dated 1960.

August 5, 1982
E. McGinty
R. Frost
R. Templin

Edward McGinty
County Surveyor

P. -124-125