

FIRST RE-ESTABLISHMENT

SPECIAL CORNER

DLC40ESE

GCDB 940020

The East Southeast corner to Donation Land Claim No. 40, located in Section 21, Township 36 South, Range 4 West, W.M.

Found rebar, 5/8 ins. diam., 3 ins. deep, inside a found iron pipe 1 1/4 ins. diam. 12 ins. deep, recognized as a monument set by F. Rhodes in 1914 on Survey for Riverdale Tracts. (See Survey No. 11200 dated 1988) The rebar is reported on Survey No. 9697, dated 1983.

To perpetuate this location, in the top of the above noted pipe and over found rebar, place a 1x12 ins. galvanized iron pipe in concrete, 3 ins. deep, with a 2 1/2 ins. diam. brass cap marked:

"CS"

+

1988

Reference the above as follows:

- Replace a found spike (C.S. traverse pt.) with a 5/8 x 24 ins. rebar, set 2 ins. deep, with a yellow plastic cap marked "Jackson C.S.", at the east edge of gravel road, brs. S40°45'14"E, 141.27 feet.
- Set a 5/8 x 24 ins. rebar, with yellow plastic cap, marked "Jackson C.S.", flush with the top of a found 2 ins. diam. pipe, projecting 1 ins. from the southeast end of a concrete parapet wall over irrigation ditch, brs. S40°46'E, 63.79 feet.
- The Northwest corner of the concrete foundation of garage to residence No. 8865, brs. S87°29'E, 54.76 feet.
- Scribe a 12 ins. diam. Black Oak "C.S." "BT", which brs. S8°28'W, 47.93 feet to center of tree at lower blaze.
- A 3/4 ins. diam. iron pipe, found 4 ins. deep, brs. N60°11'W, 5.75 feet.
- A 3/4 ins. diam. iron pipe, found 6 ins. deep, brs. N16°46'W, 19.17 feet.

Corner lies about 8 feet N45°E of the middle of North Star Lane.

June 1, 1988
R. Frost, Tech.
S. Beecher, Tech.

Edward McGinty
County Surveyor

P. 224-225