

## FIRST RE-ESTABLISHMENT

DLC43SSE

GCDB 943030

Most Southerly Southeast corner of DLC #43, Township 36 South, Range 4 West.

Found

- Original bearing tree, a 30" White Oak, which bears South 21° West, 60.72 feet as per official record.
- Also found 16" White Oak which bears North 46° West, 25.08 feet as per official distance,
- Also Black Oak down which bears North 43° East, 43.6 feet as per official record.

Set a 1½" pipe for corner,

From which:

- The original BT to Southwest bears as above-described.
- Scribed original BT, CS-BT which bears North 46° West, 25.0 feet;
- Scribed an 18" Black Oak CS-BT which bears North 45½° East, 84.7 feet.

January 28, 1944  
C. Z. Boyden  
J. H. Cushman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

**SECOND RE-ESTABLISHMENT**

**DLC43SSE**

**GCDB 943030**

South Southeast corner to DLC No. 43, T36S, R4W.

Corner lies in the Northwest quarter of Northwest quarter of Section 36.

- Found 1½ ins. diam. iron pipe exposed 2 ins. (set by C. Z. Boyden in 1944) in N-S fence line.
- Found the orig. SW BT now a 30 ins. diam. White Oak at record bearing and distance, S21°W, 60.72 feet with visible scribing in upper face.
- Also found original NW BT now a 16 ins. diam. White Oak with healed blazes, which bears record, N46°W, 25.08 feet (on slope) to estimate face upper blaze. Re-measured 24.3 feet to center of tree.
- Found 18 ins. diam., Black Oak scribed by C. Z. Boyden in 1944, N44½°E, 84.7 feet to estimated face of lower blaze. Record N45½°E, 84.7 feet. Blazes are now healed. Re-measured 85.3 feet to center of tree.
- A 3/8 ins. x 2 ins. iron bar of the type set on Champlin Subdivision bears South, 0.65 feet. Iron angle bar corner of North and West fence bears approximately South, 9.2 feet.

Scribed new BTs as follows:

- A White Oak, 5 ins. diam. bears S56°E, 15.15 feet.
- A White Oak, 6 ins. diam. bears N53°E, 20.95 feet.

Corner lies on NW slope of hill about 840 feet east of Road

June 11, 1974

R. Frost  
O. Frederick

Approved by: Edward McGinty  
County Surveyor

**NOTE:**

Set 2½ ins. diam. brass cap in top of 1½ ins. iron pipe marked:

T36S R4W
DLC
SSE
43
—
C S
1991

October 18, 1991  
T. Newcomb  
H. Durkee