

**FIRST RE-ESTABLISHMENT  
QUARTER CORNER TO SECTION 31 ONLY  
GCDB 140100**

South Quarter corner Section 31, Township 38, Range 1 West, W.M.  $V=20^\circ$ .

Found original SE BT., with old axe marks and reverse scribe of "B" and partial "T" in lower blaze. Subject tree, now a 24-inch diameter Madrone has rotted upper face. Record bearing and distance places original NW BT in a cluster of Madrone.

From original SE BT, at record bearing and distance,  $S69^\circ E$ , 19.8 feet, I set a 1-inch x 36-inch G.I. Pipe 32 inches in the ground, with a 2½-inch bronze disc marked:

T38S R1W  
¼ Section 31  
—————  
C.S. 1973  
T39S R1W

From which:

- A Douglas Fir, 5-inch diameter bears  $N25^\circ E$ , 20.5 feet to center of tree at upper blaze marked CS-BT.
- A Douglas Fir, 10-inch diameter bears  $S61^\circ W$ , 18.2 feet to center of tree at upper blaze marked CS-BT.
- A Found steel axle shaft, 1-inch diameter projection 6 inches, bears  $S3\frac{1}{2}^\circ W$ , 4.51 feet.

March 27, 1973  
Bob Malotte  
Ron Frost

Approved by:  
Edward McGinty,  
County Surveyor