

FIRST RE-ESTABLISHMENT

GCDB 300140

Quarter corner common to Sections 32 and 33, Township 38 South, Range 1 West, W.M.

Found the $\frac{5}{8}$ " iron pin, exposed 4", as set for corner by Surveyor E. A. McGinty on Recorded Survey No. 4075.

From which:

- The original bearing tree (now a 21" Black Oak with upper face open and rotted) bears $S50\frac{1}{4}^{\circ}E$, 26.7 feet to the center. (Original Record: 10" Black Oak, $S50^{\circ}E$, 27.1 feet to the face.)
- The original bearing tree (now a 12" Yellow Pine snag, plainly scribed " $\frac{1}{4}S-BT$ ") bears $S75^{\circ}W$, 37.1 feet to the face of the lower blaze (Original Record: 5" Yellow Pine, $S75^{\circ}W$, 37.6 feet.)
- The tree blazed on said recorded survey No. 4075, an 8" Yellow Pine bears $S63^{\circ}W$, 38.0 feet to the face of the blaze.

Marked new trees as follows:

- A 19" Douglas Fir, scribed "CS-BT" bears $N38^{\circ}E$, 12.2 feet to the face of the lower blaze.
- A 12" Yellow Pine, scribed "CS-BT" bears $N32\frac{3}{4}^{\circ}W$, 4.6 feet to the face of the lower blaze.

March 10, 1970
Otis Blankenship
Dan Phillips

Approved by:
M. E. Boyden,
County Surveyor