

FIRST RE-ESTABLISHMENT

GCDB 400640

Quarter corner common to sections 3 and 4, Township 38 South, Range 1 West, W.M.

No evidence of corner found, set by single proportionate measurement during the course of survey number 20414. Set a 2 ins. diam. flanged GIP, with a 3 ins. diam. brass cap MKD:

Jackson County Surveyor
T38S R1W
¼ S
4 | 3
2009
UNLAWFUL TO DISTURB

From which the following references were taken:

- 2½ ins. diam. brass cap in approximate C/L of N. Phoenix Rd. MKD:

T38S R1W
DLC
84
SW
CS
1995

brs: S77°11'51"E, 415.16 ft.

- 5/8-ins. diam. by 24 ins. long rebar with 1 ½ ins. diam. aluminum cap MKD: Jackson County Surveyor
 - ▶ Set at southerly extension of the E. side of concrete block building brs: S58°38'03"W, 388.17 ft.
 - ▶ Set at base of 4" x 4' metal gate post on S. edge of E-W gravel Rd. brs: N35°31'31"E, 577.362 ft.
 - ▶ Set at base of fence post at entrance to E-W gravel Rd. brs: S38°53'18"E, 520.65

Corner lies in unutilized field approximately 450 ft. W. of N. Phoenix Rd.

See Survey No: 20414

March 24, 2009

S. Fein
S. Beecher

Kerry Bradshaw
County Surveyor

Series II, Book I
P. -34