

## FIRST RE-ESTABLISHMENT

GCDB 540100

Quarter corner on the Township line Section 35, Township 38 South, Range 1 West and Section 2, Township 39 South, Range 1 West.

At a point on the line between the Northeast corner DLC #37, Township 39 South, Range 1 West, and the corner to Sections 34 and 35, Township 38 South, Range 1 West and Sections 2 & 3, Township 39 South, Range 1 West, on single proportion distance, I found remains of pine roots which agree with the official government record.

BT to the Southeast agrees with the official government record. BT to the Southeast also found the remains of an old pitch pine corner post, South 5.5 feet. This post no doubt has been moved south due to the wash of an irrigation ditch.

From which:

- A 6" Black Oak scribed CS-BT bears S76°E, 28.8 feet.
- Scribe an 8" Black Oak CS-BT which bears S75°W, 21.4 feet.

March 2, 1946  
C. Z. Boyden  
C. W. Bentley

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 540100

Quarter corner common to Section 35, Township 38 South, Range 1 West and Section 2, Township 39 South, Range 1 West, W.M.

Found 3 inches deep, the 1-inch diameter iron pipe reported set on First Re-establishment, page 3, in 1940.

In the top of said pipe, set in concrete, a 2½-inch diameter brass cap marked:

T38S R1W  
35  
¼S —  
2  
T39S  
C.S.  
1987

Bearing trees marked on said First Re-establishment found and measured to center of trees at lower blazes:

- Black Oak, now 14-inch diameter with blazes hidden by tree overgrowth on East-West fence wires, bears Record: S76°E, 29.06 feet. Record distance: 28.8 feet.
- Black Oak, now 20-inch diameter with double healed blazes, bears S76°W, 21.8 feet. Record: S75°W, 21.4 feet.

Corner lies 1.0 feet South of a corner post to fences bearing East-West and North at the Southeast corner of a cultivated field.

June 25, 1987  
D. Edwards  
T. Newcomb

Edward McGinty  
County Surveyor

V = 17¼°  
P. -219