

FIRST RE-ESTABLISHMENT

GCDB 600600

Section corner common to sections 1, 2, 11, 12, Township 38 South, Range 1 West, W.M.

NO evidence of corner found, set by double proportionate measurement during the course of survey number 20414.

Set a 2 ins. diam. by 30 ins. long flanged GIP, with a 3 ins. diam. brass cap MKD:

T38S R1W
1 | 2
11 | 12
2009
UNLAWFUL TO DISTURB

From which the following references were taken:

- 5/8-ins. diam. by 24 ins. rebar with a 1 1/2 ins. diam. aluminum cap, MKD: Jackson County Surveyor, Brs: S45°33'06"E, 37.94 ft. Lies approximately 25 ft. W. of N/S fence line.
- 5/8-ins diam. by 24 ins. rebar with a 1 1/2 ins. diam. aluminum cap MKD: Jackson County Surveyor, Brs: N31°34'31"W, 15.27 ft. Lies at base of apple tree.
- 20 ins. diam. W. Oak, with upper blaze "CS", lower blaze "BT", Brs: N10°13'E, 90.82 ft.
- 18 ins. diam. W. Oak, with upper blaze "CS, lower blaze "BT", Brs: S60°42'W, 206.43 ft.

Corner lies in pasture, 1 inch below the surface and approximately, 40 ft. W. of N/S fence line.

See Survey No.: 20414

March 18, 2009
S. Fein
S. Beecher

Kerry K. Bradshaw
County Surveyor

Series II, Book I
P. 28-29