

FIRST RE-ESTABLISHMENT

DLC48WNW

GCDB 848100

Re-establishment of the West Northwest corner DLC #48, Township 38 South, Range 1 West, W.M.

No definite evidence of the original corner. Found a 1" capped iron pipe for corner.

From which corner:

- A 1" iron pin bears $S\frac{1}{2}^{\circ}E$, 97.5 feet.
- The center of a 10" pear tree bears $N28^{\circ}W$, 16.3 feet.
- The SE corner of a wood frame pump house bears $N51\frac{1}{4}^{\circ}E$, 107.7 feet.
- The North corner of a 3' x 4' concrete diversion box (irrigation) bears $S51\frac{3}{4}^{\circ}W$, 52.72 feet.

Found a 1" iron pin which bears Easterly 1.25 feet.

September 3, 1947

C. Z. Boyden

L. D. Pinkham

G. L. Ray

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC48WNW

GCDB 848100

West Northwest corner to Donation Land Claim No. 48, located in Section 7, Township 38 South, Range 1 West, W.M.

Found 10 inches deep, the 1-inch pipe, with broken off cap alongside, reported on First Re-establishment, in 1947.

Remaining references noted in 1947 found:

- A 1-inch diameter pin (axle) with attached 2-inch diameter gear, found 4 inches deep, bears Easterly 1.30 feet. Record: 1.25 feet.
- The southeast corner of wood frame pump house bears Record: N51 ¼°E, 107.7 feet.

To perpetuate this location, in the top of the corner monument (1-inch pipe) set yellow plastic cap marked: JACKSON CO. C.S. and set new references:

- Rebar 5/8 x 30 inches with yellow plastic cap marked JACKSON CO. C.S., set 2 inches deep, in the middle of road along irrigation ditch, bears S8°25'E, 74.46 feet.
- Chiseled cross in the East Northeast corner of 3x3-foot concrete irrigation box, bears S55°07'W, 47.02 feet.
- Chimney (white) in the middle of large house, an estimated 400 feet distant, bears N80°30'W.

July 11, 1984
R. Frost
Edward McGinty

Edward McGinty
County Surveyor

V = 21°
P. -84