

FIRST RE-ESTABLISHMENT

DLC49NE

GCDB 845140

Northeast corner of DLC #49 on the west boundary DLC #45 (also being the Southerly L of DLC #45), Township 38 South, Range 1 West.

Found 3"x 8"x 15" sandstone with cross on top 10" below surface of road for corner; no evidence of original BTs.

- Set a $\frac{3}{4}$ " x 24" iron pin 22" in the ground which bears North 25.0 feet;
- The center of a 12" White Oak (not scribed) bears N77½°E, 277.6 feet.
- The center of a 28" White Oak bears S3°E, 234.3 feet.
- The Northeast corner of a brick foundation at the Easterly North- east corner of a bay window bears S10°55'E, 349.0 feet.

March 28, 1940

C. Z. Boyden

C. I. Bourne

A. H. Smith

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC49NE

GCDB 845140

Northeast corner of DLC #49, Township 38 South, Range 1 West, W.M.

Set a 1" x 20" galvanized iron pipe with bronze cap stamped:

T38S R1W
N.E. Cor.
C.S.
DLC NO. 49
1964

Flush with the pavement surface for corner.

From which:

- Found the $\frac{3}{4}$ " iron pin reported on the First renewal by Deputy County Surveyor, C. Z. Boyden, on March 28, 1940, which bears North 25.0 feet.
- The center of the 28" White Oak witness tree reported on said first renewal (now 30" in diameter) bears $S2\frac{1}{2}^{\circ}E$, 234.5 feet. Record: $S3^{\circ}E$, 234.3 feet.
- The center of the 12" White Oak witness tree reported on said first renewal (now 16" in diameter) bears $N77\frac{1}{4}^{\circ}E$, 277.5 feet. Record: $N77\frac{1}{2}^{\circ}E$, 277.6 feet.

The corner stone monument was not recovered as same now falls under approximately 30" or road fill.

August 10, 1964
L. D. Pinkham
L. Hart

Approved by:
M. E. Boyden,
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

DLC49NE

GCDB 845140

Northeast corner DLC #49, Township 38 South, Range 1 West, being also the Southerly "L" of DLC #45.

Found the 1" galvanized iron pipe, flush, set for corner on the Second Re-establishment on August 10, 1964. The bronze cap was missing, but the 1" pipe appeared undisturbed.

Replaced said pipe with a 3" bronze disk, set in a 20" diameter x 14" deep concrete base, 8" deep in a monument case stamped:

JACKSON COUNTY
T38S R1W
NE DLC
Cor. 49
1970
CONTROL MONUMENT

From which:

- A ¾" iron pin, 6" deep, bears N0°09'E, 25.03 feet. (First Re-establishment record of March 28, 1940: North 25.0 feet. 1964 Record: North 25.0 feet.
- The center of a 20" White Oak bears N77°22'E, 277.7 feet. 1940 Record: 12" White Oak, N77½°E, 277.6 feet. 1964 Record: 16" White Oak, N77¼°E, 277.5 feet.
- The center of a 36" White Oak bears S2°15'E, 234.6 feet. 1940 Record: 28" White Oak, S3°E, 234.3 feet. 1964 Record: 30" White Oak, S2½°E, 234.5 feet.

March 28, 1972
Lloyd Shreeve
Ray Webber

Approved by:
Mark E. Boyden
County Surveyor

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

DLC49NE

GCDB 845140

Northeast corner to Donation Land Claim No. 49, identical with the Southerly Ell Corner of Donation Land Claim No. 45, located in Section 8, Township 38 south, Range 1 West, W.M.

Found 8 inches deep in monument case, the brass cap described on Third Re-establishment in 1972.

References reported in 1972 found:

- A $\frac{3}{4}$ -inch diameter iron pin, found flush, bears $N0^{\circ}01'E$, 25.8 feet. Record: $N0^{\circ}09'E$, 25.03 feet.
- White Oak, 19-inch diameter, bears $N77^{\circ}27'E$, 277.50 feet to center. Record: $N77^{\circ}22'E$, 277.7 feet.

To perpetuate this location, take new references as follows:

- White Oak, 32-inch diameter (note scribed), bears $S2^{\circ}13'E$, 296.68 feet to center of tree at base.
- Set $\frac{5}{8}$ x30-inch rebar, 28 inches in the ground, with yellow plastic cap marked: "JACKSON County C.S." bears $S31^{\circ}51'E$, 27.34 feet.
- Found a $\frac{1}{2}$ -inch diameter pin, inside a $\frac{1}{2}$ -inch pipe, being the point of intersection of Voorhies and Carpenter Hill Road, bears $S89^{\circ}53'50"E$, 729.94 feet.
- The Southeast corner of Donation Land Claim No. 48 bears $N89^{\circ}50'21"W$, 251.16 feet.

Corner lies in the middle of Carpenter Hill Road, about 3 feet East of the intersection of Private road c. South to residence 135 Carpenter Hill Road.

July 11, 1984
R. Frost
Edward McGinty

Edward McGinty
County Surveyor

P. -82