

FIRST RE-ESTABLISHMENT

DLC51NE

GCDB 851101

NE corner DLC #51, Township 38 South, Range1 West, W.M.

Found original BT to SE with scribe visible; also stump hole of BT to SW.

From which:

- Set 1½ x 36 inch galvanized pipe for corner.

From which:

- A 12" White Oak bears N56°50"W, 102.0 feet;
- An 8" White Oak bears S63°15'W, 9.3 feet.

April 26, 1929
C. Z. Boyden,
Deputy County Surveyor

Ralph McKay, Chainman
Jim Beddingfield, Chainman

SECOND RE-ESTABLISHMENT

DLC51NE

GCDB 851101

Northeast corner of DLC No. 51, Township 38 South, Range 1 West, W.M.

Found the 1½" galvanized iron pipe corner monument flush with the ground surface, as set on the First renewal by Deputy County Surveyor, C. Z. Boyden in 1929.

From said corner monument:

- The Northwest witness tree established in 1929 (now a 20" White Oak with upper blaze rotted and the lower blaze left intact, bears N56°50'W, 101.7 feet.
- The center of the stump hole of the down witness tree established in 1929 (said down tree being scribed CS), bears S63°15'W, 9.7 feet.
- A ¾" iron pipe set for corner on Recorded Survey No. 1984 bears N31°E, 3.03 feet.

From the 1½" galvanized iron pipe corner monument, I establish new references as follows:

- A 12" White Oak, scribed CS-BT bears S17°20'E, 14.4 feet to the face of the upper blaze.
- A 16" White Oak, scribed CS-BT bears S88°10'W, 73.6 feet to the face of the upper blaze.

Note: True bearings, rounded to the nearest 05', were used for meridian control.

March 16, 1963

F. A. Roberts

B. T. Austin

Approved by:

M. E. Boyden,

County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

DLC51NE

GCDB 851101

Northeast corner to DLC No. 51, located in Section 18, Township 38 South, Range 1 West, W.M.

At the corner, found 6 inches deep, the 1½-inch diameter iron pipe reported on Second Re-establishment in 1963.

In the top of found pipe in cement, set a 2½-inch diameter brass cap marked:

T38S R1W
DLC
NE C.S.
51
1984

A bearing tree marked on First re-establishment in 1929 and reported in 1963, a double White Oak, the Easterly fork of which, now 20 inches in diameter, containing scribe marks in exposed (upper) face, bears N56°50'W, 101.91 feet to center of said fork at face. Record: (1929) 102.0 feet.

Bearing trees marked in 1963 found and re-measured to center of trees at lower blaze:

- White Oak, 16-inch diameter with healed blazes, bears S17°20'E, 15.00 feet. Record: 14.4 feet (upper face)
- White Oak, 17-inch diameter with healed blazes, bears S88°10'W, 74.20 feet. Record: 73.6 feet (upper face)
- A ¾-inch diameter iron pipe, found 12 inches deep. Set (erroneously) for the corner on Survey No. 1984 in 1962, bears N31°30'E, 2.98 feet. Record: (Second re-establishment) N31°E, 3.03 feet.
- A found 5/8-inch diameter iron pin (reference: Survey NO. 583, dated 1953), located 1 foot South of Easterly-Westerly fence line, bears S1°09'W, 10.05 feet.

Corner lies an estimated 250 feet, S39°W, of the center of the West end of large barn.

October 30, 1984

E. McGinty

R. Frost

Witness: Paul Hadath, Resident

Edward McGinty

County Surveyor

V = 18½°

p. -117

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

DLC51NE

GCDB 851101

Northeast corner to Donation Land Claim No. 51, located in Section 18, Township 38 South, Range 1 West, W.M.

The monument (pipe and brass cap) reported on Third Re-establishment, in 1984, is now covered with concrete slab (floor of pig pen).

From extant references, noted in 1984, set lead and tack, in drill hole in concrete floor, over previous monument.

From which: Bearing trees, White Oaks, with healed blazes noted in 1984 bears as follows to center of trees at lower blaze:

- 17-inch diameter, bears S17°56'27"E, 14.98 feet.
- 18-inch diameter, bears S88°00'48"W, 74.19 feet.
- 22-inch diameter, bears N56°58'53"W, 101.93 feet.
- A $\frac{5}{8}$ ins. (outside diameter) iron pipe, found 4 inches deep, bears S1°32'34"W, 10.07 ft.

As occupying the above-noted lead and tack amongst a herd of hogs may prove difficult, set a reference monument:

- 1x30-inch galvanized iron pipe 29 inches in the ground with Jackson County brass cap marked:

"R.M."

o

1996

bears S88°47'18"W, 24.53 feet.

- The reference monument is further referenced by a $\frac{5}{8}$ x 24-inch rebar, set flush, with Jackson County metal cap, bears N87°54'59"W, 46.66 feet. This rebar is located 3½ feet south of the corner to north and east bearing fence lines.

Also center punched metal caps, atop the 1 inch (outside) diameter, pipe corners of pig pin, bears:

- NW corner: N69°56'20"E, 22.60 feet.
- SW corner: S83°39'07"E, 20.80 feet.

Current resident: R. Christenson, 3960 Independence School Road

Basis of bearings: Point Nos. 8 & 9, survey for L. Trovato, courtesy of Hoffbuhr Surveying.

March 6, 1996
R. Frost, Tech.
S. Beecher, Tech.

Roger Roberts
County Surveyor

P. -12