

FIRST RE-ESTABLISHMENT

DLC63SE

GCDB 863130

Southeast corner to DLC No. 63, identical with the West Southwest corner to DLC No. 65, located in Section 26, Township 38 South, Range 1 West, W.M.

Found 7 inches deep:

- The $\frac{3}{4}$ -inch diameter iron pipe reported on Survey No. 3059, to be subject DLC corner.
- A found iron bar, reported to be the East-Northeast corner of DLC No. 66, bears N89°27'50"E, 175.03 feet.

SEE Survey No. 2766 and 4525.

Mound stones around found pipe and to perpetuate this location, take new references:

- English Walnut, 20-inch diameter, bark-scribed "CS" bears N64°09'E, 52.90 feet to center of tree at (upper) scribe.
- English Walnut, 21-inch diameter, bark-scribed "CS" bears, N29°21'W, 84.10 feet to center of tree at (upper) scribe.

Corner lies about 260 feet East of creek, 0.6 feet South of East-West fence line and 2.3 feet S70°E of steel fence post.

January 29, 1985
R. Frost
E. McGinty

Edward McGinty
County Surveyor

P. 127-128