

FIRST RE-ESTABLISHMENT

DLC64NW

GCDB 863100

Northeast corner to Donation Land Claim No. 63, also being the Northwest corner to Donation Land Claim No. 64, located in Section 23, Township 38 South, Range 1 West, W.M.

Found 10 inches deep the 2-inch diameter iron pipe reported on Survey No. 3056, dated 1966, with what appears to be a 2 feet long section of old car spring inside.

Removed found spring and inside said 2-inch pipe, set a 1x36-inch Galvanized iron pipe, 34 inches in the ground with a 2½-inch diameter brass cap marked:

JACKSON COUNTY 1984



To perpetuate this location.

References noted on Survey No. 3056 found:

- A double Black Walnut, 26-inch diameter at base, (not scribed) bears N82°50'E, 25.70 feet to center of tree at base. Record: N83°30'E.
- A 5/8-inch pin, found 12 inches deep on North-South (board) fence line, bears S0°58'W, 20.33 feet. Record: S0°45'W, 20.39 feet.
- The Northeast corner of the concrete foundation of wood frame house bears S8°45'W, 132.23 feet. Record: 132.20 feet.
- The iron pin reported 20.75 feet westerly could not be found

Deposited the above-noted "spring" alongside corner and took additional references:

- Iron pipe, 2-inch diameter, projecting 5 feet, bears N23°58'E, 8.80 feet to center at base.
- Ash, 5-inch diameter (not scribed) bears N50°W, 2.95 feet to center of tree at base.

Corner lies in blackberry bushes at the intersection of South (board) and East-West (page wire) fences, in the (Northeast corner) back yard of residence 202 North First Street (Talent).

October 29, 1984

R. Frost

E. McGinty

Edward McGinty

County Surveyor

P. -126