

FIRST RE-ESTABLISHMENT SPECIAL CORNER

DLC65NW

GCDB 863140

Northwest corner of Donation Land Claim No. 65, located in Section 26, Township 38 South, Range 1 West, W.M.

Utilizing data gathered during the execution of Survey No. 11287, at a proportionate distance, set a 1x36-inch Galvanized iron pipe 42 inches in the ground.

In the top of said pipe, set in concrete, a 2½-inch diameter brass cap marked:

T38S R1W
+
CS
1988

Take references as follows:

- The Southeast corner of a concrete foundation of a house at 517 Wagner Creek Road bears S66°23'53"W, 47.74 feet.
- The Northeast corner of the same foundation bears N64°37'48"W, 48.88 feet.
- A 5/8-inch diameter rebar with broken plastic cap, found flush at the Southeast corner of Lot 6, Taylor Subdivision bears N21°56'52"W, 37.04 feet.

Corner lies in a field, about 15 feet East of the East line of said Lot 7.

See Job File 88-57.

August 15, 1988
D. Edwards, Tech.
T. Newcomb, Tech.

Edward McGinty
County Surveyor

P. -320