

FIRST RE-ESTABLISHMENT

SPECIAL CORNER

DLC72SW

GCDB 872110

Southwest Corner of Donation Land Claim No.72, located in Section 36, Township 38 South, Range 1 West, W.M.

Found unrecorded 3 inches diameter brass cap set in concrete protruding 6 inches aboveground marked:

T38S	R1W
SW	
COR	DLC
	72
CS	
1972	

Note: For establishment of this unrecorded monument see Reference Book Survey No. 5011 1972, page 10.

References found from Survey No. 2886, dated 1965:

- 1¼-inch diameter splined axle, protruding 4 inches aboveground, bears N40°16'00"E, 20.91 feet. Record: S40°16'W, 20.81 feet.
- 3½-inch diameter gear end of axle, protruding 4 inches aboveground, bears N43°19'54"W, 57.51feet. Record: S43°32'E, 57.49 feet.
- 5⁄8-inch diameter bolt protruding, protruding 3 inches aboveground, bears N89°34'48"W, 66.12 feet. Record: S89°57'55"W, 66.27 feet.

Corner lies 1½ feet North of fence. Fence corner is 11 feet East with fence lines projecting West and South.

October 1, 1999

T. Newcomb

J. Burgess

Roger Roberts

County Surveyor

P. -59