

## FIRST RE-ESTABLISHMENT

GCDB 100140

Quarter corner common to Section 36, Township 39 South, Range 2 East and Section 31, Township 39 South, Range 3 East.

Set 1"x36" galvanized iron pipe 30" in the ground with a 2½" bronze cap stamped:

T39S R2 & 3E  
¼ 36 | 31 Cor.  
C.S.  
1969

From which:

- The original bearing tree (now an 18" Black Oak, plainly scribed) bears N33°E, 167.6 feet to the face of the upper blaze;
- Found the original southwest bearing tree, plainly scribed, bulldozed out by logging operations.

From said pipe corner, I establish the following new bearing trees:

- A 6" White Oak, scribed "CS-BT", bears S40°W, 21.8 feet to the face of the lower blaze;
- An 18" Fir, scribed "CS-BT", bears S75¼°E, 80.8 feet to the face of the lower blaze.

August 20, 1969  
G. Kaiser  
O. Blankenship

Approved by:  
Mark Boyden,  
County Surveyor