

FIRST RE-ESTABLISHMENT

GCDB 300240

Quarter corner common to Sections 28 and 29, Township 39 South, Range 3 East, W.M. $V = 17\frac{1}{2}^\circ$

Found 2-inch diameter, Galvanized iron pipe projecting 18 inches from the ground in a mound of stone. Pipe marked as follows:

WEST SIDE	EAST SIDE
T39S	R
R3E	C
$\frac{1}{4}$	E
S29 S28	
1973	7
	2
	8
	2

From said pipe,

- An original BT, a Fir, now 63-inch diameter, containing bark scribed " $\frac{1}{4}$ S" and partial "T", bears record, S20°E, 93.06 feet.
- Location of original NW tree falls in "skid" road. No evidence found.

I marked the following trees CS BT and took measurements to center of tree at lower blaze:

- A Douglas Fir, 14-inch diameter, bears N83°50'E, 22.5 feet.
- A White Fir, 13-inch diameter, bears N23°50'W, 29.6 feet.

October 29, 1973
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor