

## FIRST RE-ESTABLISHMENT

GCDB 600700

First Re-establishment per GLO, 1917.

## SECOND RE-ESTABLISHMENT

GCDB 600100

Section corner common to Section 35 and 36, Township 39 South, Range 3 East and Section 1 and 2, Township 40 South, Range 3 East, W.M.  $V = 16^\circ$

Found monument set on First Re-establishment (1917) by F. W. Rodolf, a 2-inch diameter iron pipe, projecting 12 inches, with attached GLO brass cap marked:

|      |     |
|------|-----|
| T40S | R3E |
| S35  | S36 |
| S2   | S1  |
| 1917 |     |

**Note:** Not stamped as recorded.

A BT marked by Rodolf,

- Now a sawed Fir stump, rotted with old axe work in evidence bears Record:  $N65^\circ E$ , 24.42 feet to center.

Original BTs marked by E.T.T. Fisher in 1858 and subsequently recorded by Rodolf found as follows:

- The stump depression of a down and decayed Fir, containing axed face, bears Record:  $S45^\circ E$ , 27.72 feet.
- A Cedar, 31-inch diameter, with healed blaze bears  $S85^\circ W$ , 24.5 feet to center of tree. Record:  $S85^\circ W$ , 23.10 feet.
- A Cedar, 29-inch diameter, with healed blaze, bears Record:  $N10^\circ W$ , 34.98 feet to center of tree.

I marked the following new trees CS BT and took measurements to center of trees at lower blaze:

- A White Fir, 10-inch diameter, bears  $S81\frac{1}{2}^\circ E$ , 28.6 feet.
- A Douglas Fir, 10-inch diameter, bears  $N59^\circ E$ , 34.0 feet.

October 16, 1973  
Ed Graham  
B. Malotte  
R. Frost

Approved by: Edward McGinty  
County Surveyor