

FIRST RE-ESTABLISHMENT

GCDB 700500

Section corner common to Sections 12 and 13, Township 39 South, Range 3 East, and Sections 7 and 18, Township 39 South, Range 4 East, W.M.

At the corner found projecting 4 inches in mound of stone, 2-inch diameter galvanized iron pipe with standard BLM brass cap marked:

T39S	
R3E,R4E	
S12	S7

S13	S18
1967	

Original bearing trees marked by S. Truax in 1859 found:

- Sawed Fir stob, 38-inch diameter, with healed blazes, bears S25°E, 14.79 feet to center. Record: S20°E, 13.86 feet.
- Rotted Fir stob, 21-inch diameter, scribed "T39S R3E S13" in exposed upper face bears S58°W, 14.45 feet to scribed face. Record: S58°W, 15.84 feet.

Bearing trees marked by the BLM in 1967 found with healed single blazes and measured to center of trees:

- White Fir, 16-inch diameter, bears N3°E, 53.00 feet. Record: 52.80 feet.
- White Fir, 21-inch diameter, bears S41°W, 42.24 feet. Record: 42.90 feet.
- White Fir, 19-inch diameter, bears N27°W, 68.81 feet. Record: N27°W, 68.64 feet.

Marked a new tree "CS" "BT":

- White Fir, 14-inch diameter, bears S88½°E, 49.75 feet to center of tree at lower blaze.

Corner lies about 26 feet South of dirt road C. East-West.

August 2, 1983
R. Frost
B. Malotte

Edward McGinty
County Surveyor

V = 19°
P.-74