

**FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 32 ONLY
GCDB 240100**

South quarter corner of Section 32, Township 39 South, Range 4 East, W.M. $V = 21^\circ$

From the following evidence, at the location described below, I set a 1 x 36-inch Galvanized iron pipe 12 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1974
T39S R4E
¼S 32
——
T40S

Original BTs recorded by E.T.T. Fisher in 1858 found as follows:

- The base of a dead and down Juniper, 12-inch diameter, scribed "¼S" and "BT" in exposed faces bears record, S10°W, 3.96 feet.
- A rotted Juniper stump, 10-inch diameter, containing scribe marks in weathered face bears Record: N70°W, 6.60 feet to scribed face.

I mounded stones around corner, marked the following trees CS BT and took measurements to center of trees at lower blaze:

- A Ponderosa Pine, 8-inch diameter bears N86°E, 36.80 feet.
- A Ponderosa Pine, 12-inch diameter bears S37°E, 23.15 feet.

Corner lies on top of ridge 3½ feet South of East-West fence.

December 17, 1974
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor