

FIRST RE-ESTABLISHMENT

GCDB 240300

Quarter corner common to Sections 20 and 29, Township 39 South, Range 4 East, W.M. $V = 20\frac{1}{2}^\circ$

Found, $\frac{5}{8}$ x 30-inch re-steel rod with aluminum cap, projecting 10 inches in mound of stone, with the original stone (disturbed), marked by P. Applegate in 1893, alongside, as reported on Survey No. 4754, dated 1971.

I replaced said rod with a 1 x 36-inch Galvanized iron pipe set 24 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975
T39S R4E
20
¼S —
29

Original BTs found as follows:

- Juniper, 23-inch diameter, scribed "¼S" and "BT" in exposed faces bears $S57^\circ E$, 73.92 feet to lower face. Record, $S57^\circ W$, 73.92 feet.
- Black Oak, 12-inch diameter, containing scribed "S" in partially exposed upper face bears $N53^\circ W$, 16.50 feet to scribed face. Record: $N53^\circ E$, 16.50 feet.

I deposited found re-steel rod alongside corner and marked a new tree CS BT:

- Cedar, 13-inch diameter bears $N15\frac{1}{2}^\circ E$, 23.57 feet to center of tree at lower blaze.

Corner lies about 600 feet North of location marker on 8-inch diameter Juniper in draw, near irrigation canal.

August 12, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor