

FIRST RE-ESTABLISHMENT

GCDB 300540

Quarter corner common to sections 8 and 9, Township 39 South Range 4 East, W.M.

Found the 1966 BLM Cadastral Survey monument, set during the re-monumentation of certain original corner points, being a 2 ½ ins. diam. GIP with a 3 ins. diam. brass cap, exposed 1 ins. MKD:

USDI
T39S R4E
1/4
S8 | S9
1966
CADASTRAL SURVEY
BLM

Found basalt stone with ¼ buried alongside.

Bearing Tree recorded by the BLM in 1966, found:

- Cedar, dead and down, size indeterminate with partially healed blaze with "S9 B" visible, Brs. record: S87°E, 41 lks to root hole.

Mark new bearing trees "CS" "BT" and take measurements to center of tree at lower blaze:

- D. Fir 7 ins., brs. N84 ½°E, 29.25 ft.
- W. Fir 7 ins., brs. S9 ½°E, 31.50 ft.
- D. Fir 12 ins., brs. S26 ½°W, 37.70 ft.
- D. Fir, 8 ins., brs. N66°W, 21.30 ft.

Corner lies approx. 300 ft. south of spring branch course, E-W.

V18°E

July 5, 2011

S. Fein

Kerry K. Bradshaw
County Surveyor

Series II Book I
P. -18