

FIRST RE-ESTABLISHMENT

GCDB 340300

Quarter corner common to Sections 21 and 28, Township 39 South, Range 4 East, W.M. $V = 16^\circ$

Found, the Pine, recorded as the corner, by P. Applegate in 1893, now down, 10-inch diameter, scribed " $\frac{1}{4}$ S".

I set a 1 x 36-inch diameter Galvanized iron pipe 12 inches in the center of the stump, of said tree, with a 2½-inch bronze disc marked:

Jackson County 1975
T39S R4E
21
 $\frac{1}{4}$ S —
28

The only remaining original BT, now a down and rotted White Fir, 21-inch diameter scribed " $\frac{1}{4}$ ", the stump of which bears Record: S32½°E, 17.82 feet to estimated lower face.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Cedar, 17-inch diameter, with "W" nail in base bears N26°E, 27.11 feet.
- Cedar, 14-inch diameter bears S21°W, 1.30 feet.
- The reference marker set on Survey No. 5552, file date 1974, a 5/8-inch re-steel rod, projecting 6 inches with aluminum cap bears N73°E, 3.3 feet. Record: N87°19'E, 3.3 feet.

Corner lies on blazed East-West line, about 300 feet West of road.

September 11, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor