

FIRST RE-ESTABLISHMENT

GCDB 440300

Quarter corner common to Sections 22 and 27, Township 39 South, Range 4 East, W.M. $V = 20\frac{1}{2}^\circ$

Found, original NW BT, a Douglas Fir, now 32-inch diameter, containing scribed partial "4" and "S" visible in partially opened upper face.

From the preceding evidence I set a 1 x 36-inch Galvanized iron pipe 28 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975
T39S R4E
22
¼S —
27

From which, the above original BT, recorded by S. Truax in 1859 bears Record: N25°W, 12.54 feet to scribed upper face.

- The original SE BT is now gone.
- A found metal fence post, in mound of stones bears N39°W, 8.40 feet. See Survey No. 5552, file date 1974.

I mounded stones around corner, marked new trees CS BT and took measurements of center of trees at lower blaze:

- Douglas Fir, 19-inch diameter bears N66°E, 27.36 feet.
- White Fir, 18-inch diameter bears S30½°E, 34.41 feet.

Corner lies on steep West slope an estimated 230 feet East of creek, and about 575 feet West of location marker on 20-inch diameter Pine, alongside road.

August 13, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor