

FIRST RE-ESTABLISHMENT

GCDB 640700

Quarter corner common to Section 36, Township 38 South and Section 1, Township 39 South, Range 4 East, W.M.

Found at the corner position, exposed 14 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1973, marked:

T38S R4E
S36
¼—
S1
T39S
1973

Single remaining original bearing tree recorded by S. Truax of the GLO in 1859:

- A P. Pine, now 40 ins. diam. with healed blazes, brs. S 36° E, 27.1 ft. to center at base. Record; 28.1 ft. to face.

Bearing tree recorded by the BLM in 1973:

- A P. Pine high-stump with a healed single blaze, brs. record; N 3½° W, 36.0 ft. to center at base.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- S. Pine 7 ins. diam. brs. N 66¼° E, 15.6 ft.
- D. Fir 8 ins. diam. brs. S 64° W, 8.0 ft.

Corner lies approx. 900 ft. east of logging road.

November 6, 2012

H. Durkee

Scott Fein
Deputy Jackson County Surveyor

P. – 71

V. – 16°10'