

FIRST RE-ESTABLISHMENT

GCDB 400600

Section corner common to Sections 3, 4, 9 and 10, Township 40 South, Range 3 West, W.M.
 $V = 18^\circ$

At the corner found an 18 x 12 x 10-inch stone (unmarked) and firmly in place as set by S. W. Lackland in 1882.

I replaced said stone with a 1 x 36-inch Galvanized iron pipe projecting 4 inches with 2½-inch diameter bronze disc marked:

JACKSON COUNTY 1980	
T40S R3W	
4	3
9	10

From which I found the following references recorded by above surveyor:

- Douglas Fir, 28-inch diameter with healed double blazes bears Record: $N13^\circ E$, 20.46 feet to estimated face. Re-measure to center of tree at lower blaze, 21.29 feet.
- Douglas Fir, 19-inch diameter with "W" scribe visible in partially open upper face bears East, 11.36 feet to scribed face. Record: $S64^\circ E$, 10.56 feet.
- Laurel, 14-inch with healed double blaze bears $S50^\circ W$, 33.91 feet to center of tree at lower blaze. Record: $S45^\circ W$, 36.30 feet.
- Douglas Fir, 14-inch diameter with healed double blaze bears $N49\frac{1}{2}^\circ W$, 13.41 feet to center of tree at lower blaze. Record: $N42^\circ W$, 13.20 feet.

I marked new tree "CS" "BT":

- Douglas Fir, 20-inch diameter bears $S64^\circ E$, 17.03 feet to center of tree at lower blaze.
- I drove an angle iron with monument sign attached 2 feet Southerly and raise mound of stone around corner with original stone alongside.

Corner lies in draw course $N30^\circ W$, on 60% slope.

- Set location marker on Douglas Fir, 21-inch diameter on South side of road, 1640 feet North of center.

January 21, 1980
B. Malotte
J. Gallegos

Approved by: Edward McGinty
County Surveyor