

FIRST RE-ESTABLISHMENT

GCDB 640100

Quarter corner common to Section 36, Township 40 South, Range 3 West and Section 1, Township 41 South, Range 3 West, W.M.

From the following evidence at the location described below, set at the corner 1 x 36-inch Galvanized iron pipe, 30 inches in the ground, with a 2½-inch diameter bronze cap marked:

Jackson County 1981
T40S R3W
36
¼S —
1
T41S

From which original bearing trees recorded by S. Lackland in 1882 found:

- Ponderosa Pine, 15-inch diameter, with healed blazes bears Record: N46°E, 23.76 feet to estimated lower face. Re-measured to center of tree, 24.05 feet.
- Black Oak, 22-inch diameter, now dead and leaning West, containing scribed "B" in opened, rotted lower face bears Record: S72°W, 7.92 feet to estimated original position of scribed face.

Original stone not found.

Bearing trees marked on Survey 4767 in 1971 found:

- Douglas Fir, 10-inch diameter, with scribe marks visible in partly healed blazes bears N16°E, 17.40 feet to center. Record: N19¼°E.
- Douglas Fir, 7-inch diameter, with scribe marks visible in partly healed blazes bears S65°E, 16.60 feet to center. Record: S61¼°E.

Note: The 1½-inch (outside) diameter iron pipe, monument set on above-noted survey is found removed from and lying on the ground.

November 23, 1981

R. Frost

R. Templin

Witness: T. Newcomb USFS

Edward McGinty

County Surveyor

V = 16°

P. -191