

FIRST RE-ESTABLISHMENT

GCDB 300500

Section Corner common to Sections 8,9,16 and 17, Township 41 South, Range 2 West, W.M.

Found projecting 18 inches in a broken down mound of stone, the 2-inch diameter iron pipe, recorded as set by Fred W. Rodolf in 1915 with a standard 2½-inch diameter brass cap marked:

T41S R2W	
S8	S9
S17	S16
1915	

Note: pipe was leaning to the west, straightened pipe and rebuilt mound of stone.

Original bearing trees recorded by E. B. Henry in 1908 and found by Rodolf in 1915, found and measured to the center of tree at base:

- Ponderosa Pine 33-inch diameter with healed blaze bears N77½°E, 47.40 feet. Record 46.86 feet.
- Sawed Ponderosa Pine stump 40-inch diameter bears S35½°E, 22.01 feet. Record 21.12 feet.

No trees found at the record position of the Southwest and Northwest bearing trees.

Marked new trees 'CS BT' and measured to the center of tree at lower blaze:

- Douglas Fir 9-inch diameter bears S07°W, 21.35 feet.
- Ponderosa Pine 7-inch diameter bears N83¾°W, 29.90 feet.

Original blazed line North of corner.

September 15, 2000

T. Newcomb

S. Beecher

V = 14°

P. -50