

FIRST RE-ESTABLISHMENT

GCDB 700540

Quarter corner common to Section 7, Township 41 South, Range 1 West, and Section 12, Township 41 South, Range 2 West, W.M.

Found at the corner position, exposed 11 ins., the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the GLO in 1916, marked:

S12 | S7
1916

Original bearing trees recorded by F. Rodolf of the GLO in 1916, found with healed blazes and measured to center at base:

- S. Fir, now 18 ins. diam. brs. S89°E, 22.1 ft. record; S 78° E, 19.8 ft.
- S. Fir, now 34 ins. diam. brs. record; S60°W, 68.0 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- S. Fir 17 ins. diam. brs. N35°W, 5.1 ft.
- No other trees of size practical in northeast quadrant.

Corner lies on a 50% slope approx. S 45° E, 700 ft. from intersection of dirt road and top of ridge.

July 31, 2012
H. Durkee

Scott Fein
Deputy Jackson County Surveyor

P. – 17
V. – 13°20'