

GCDB 500100

80.0 Chains

A point about 140 feet below last Section corner, set a basalt stone 14x10x5-inch, 9 inches in the ground, for corner to Sections 2, 3, 34 and 35, marked with 2 notches on E. and 4 notches on W. edges.

From which:

- A white fir, 24-inch diameter bears S.51°W., 25 links, marked **T31S R2E S3 BT.**
- A white fir, 16-inch diameter bears N.24°W., 51 links, marked **T30S R2E S34 BT.**
- A white fir, 10-inch diameter bears S.66°E., 35 links, marked **T31S R2E S2 BT.**
- A white fir, 24-inch diameter bears N.36°E., 50 links, marked **T30S R2E S35 BT.**

RETRACEMENT

From the corner of Sections 1, 2, 35, and 36. West, between Sections 2 and 35.

40.00 Find no evidence of ¼ Section cor.

80.33 Fall 114 links S. of corner of Sections 2, 3, 34 and 35.

SEE NEXT PAGE FOR RE-ESTABLISHMENT

RE-ESTABLISHMENT

GCDB 500100

79.76

A point 40.00 chains in departure from the $\frac{1}{4}$ Section corner of Section 35 only, previously described.

Set an iron post, 3 feet long, 2-inch diameter, 27 inches in the ground, for corner of Sections 34 and 35 only, with brass cap marked:

T30S	R2E
S34	S35

T31S R2E	
S 2	
1937	

From which:


- A white fir, 20-inch diameter bears N.71°E., 128 links distance. Marked: **T30S R2E S35 BT.**
- A white pine, 25-inch diameter bears N.22°W., 58 links distance. Marked: **T30S R2E S34 BT.**

SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 34 AND 35 ONLY
GCDB 500100**

Section corner common to Sections 34 and 35 only, Township 30 South, Range 2 East, W.M.

Found projecting 8 inches, the 2-inch diameter iron pipe with GLO brass cap marked:



As recorded by L. Carter in 1937.

An original bearing tree recorded by Carter found as follows:

- The base and stump remains of a tipped-over White Fir, 21-inch diameter, scribed "T30R2ES35BT" bears Record: N71°E, 84.48 feet
- Northwest bearing tree now gone.

The brass cap corner of Sections 2 and 3 bears N89¼°W, 38.16 feet. Record: N89°11'W, 38.28 feet.

I marked new trees CS BT:

- White Pine, 11-inch diameter bears N21¾°E, 35.22 feet to center of tree at lower blaze.
- Cedar, 43-inch diameter bears S55°W, 4.34 feet to scribed lower face.

May 9, 1978
B. Malotte
R. Frost

Edward McGinty
County Surveyor

V = 20¼°

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

**SECOND RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 34 AND 35 ONLY
GCDB 500100**

Section corner common to Sections 34 and 35 only, Township 30 South, Range 2 East, W.M.

Found 2½ ins. diam. brass cap on 2 ins. diam. galvanized iron pipe, exposed 1 foot, and marked:

U.S. GENERAL LAND OFFICE SURVEY

T30S R2E	
S34	S35
T31S R2E	
S2	
1937	

As recorded by L. Carter in 1937.

Bearing trees recorded on First Re-establishment in 1978 are either burnt away by a forest fire or dead and down.

New references;

Bearing tree marked for the corner of Sections 2 and 3 only T31S R2E found:

- Fir 24 ins. diam. with double healed blazes, bears N75°48'03"W, 66.62 feet to center of tree lower blaze

Mark new bearing trees and measure to center of tree at lower blaze :

- Fir 11 ins. diam. scribed "CS" in the upper and "BT" in the lower blaze, bears S01°23'00"W, 19.81 feet.
- Fir 11 ins. diam. scribed "CS" in the upper and "BT" in the lower blaze, bears N26°28'56"W, 17.94 feet.

The brass cap corner of Sections 2 and 3 bears record N89¼°W, 38.18 feet. Record: 38.16 feet.

Corner located approximately 75 ft. Northerly of Abbott Creek Rd.

November 28, 2017
J. Hall
B. Paull

Scott D. Fein
Jackson County Surveyor