

GCDB 640100

40.00 Chains

Set stone, 20x4x7-inch 6 inches deep in mound of stone on bedrock, for $\frac{1}{4}$ s. corner, marked $\frac{1}{4}$ on N. face.

- A hemlock, 12-inch diameter bears S.78°E., 22 links, marked $\frac{1}{4}$ S BT.
- A hemlock, 10-inch diameter bears N.7°W., 27 links, marked $\frac{1}{4}$ S BT.

Surveyed by P. Applegate in August 4, 1891

RETRACEMENT

From the corner of Townships 30 and 31 S., Ranges 2 and 3 E. West, between Sections 1 and 36:

39.80 Fall 58 links, S. of $\frac{1}{4}$ Section corner.

80.24 Fall 93 links, S. of corner of Sections 1, 2, 35 and 36.

RE-ESTABLISHMENT

QUARTER CORNER TO SECTION 36 ONLY

GCDB 640100

40.00

A point 40.00 chains in departure from the corner of Townships 30 and 31 S., Ranges 2 and 3 E., previously described.

Set an iron post, 3 feet long, 1-inch diameter, 28 inches in the ground, for $\frac{1}{4}$ Section corner of Section 36 only, with brass cap marked:

$\frac{1}{4}$ S 36
—————
1937

From which:

- A white pine, 28-inch diameter bears N.63°E., 110 links distance. Marked: $\frac{1}{4}$ S 36 BT.
- A fir, 30-inch diameter bears N.58°W., 46 links distance. Marked: $\frac{1}{4}$ S 36 BT.

Surveyed by L. Carter in 1937.

SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT

FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 36 ONLY
GCDB 640100

South Quarter corner of Section 36 only, Township 30 South, Range 2 East, W.M.

Found at the corner position, exposed 7 ins., the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the GLO in 1937, marked:

$\frac{1}{4}$ S36

1937

Bearing trees recorded by L. Carter of the GLO in 1937 found and measured to center of trees at base:

- W. pine sawed stump with exposed weathered face brs. N 63° E, 73.5 ft. Record; 72.6 ft. to face.
- D. fir now 34 ins. diam. with healed blaze brs. N 58° W, 31.4 ft. Record; 30.4 ft. to face.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- Hemlock 5 ins. diam. brs. N 44° W, 7.3 ft.

1937 GLO monument for ¼ corner of Section 1 only, brs. east, 13.2 ft.

Corner lies approx. 500 ft. southerly of dirt road intersection on 50% slope.

August 6, 2008

H. Durkee

B. Beeman

Roger R. Roberts

Jackson County Surveyor

P. – 158

V. – 18°