

FIRST RE-ESTABLISHMENT

GCDB 200100

Section corner common to Sections 31 and 32, Township 32 South, and Sections 5 and 6, Township 33 South, Range 1 West, W.M.

Found at the corner position, exposed 7 ins., the 2 ins. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the BLM in 1957, marked:

T32S R1W
S31 | S32
—+—
S6 | S5
T33S
1957

A 2 ins. diam. galv. iron pipe, also exposed 7 ins., stands adjacent to said monument on the east side.

Original bearing trees recorded by Nathaniel Ford of the GLO in 1855, found and measured to center at base:

- Pine, dead, down and rotted, with indiscernible scribe marks on a weathered face brs. record; N 45° E, 24.4 ft.
- Rotted Pine remains br. record; S 35° E, 8.6 ft.
- Madrone rotted remains br. record; N 55° W, 37.6 ft.

Bearing trees recorded by the BLM in 1957, found and measured to center at base:

- Cedar, now 36 ins. diam. with scribe marks "T32SR1WS32BT" in partially healed single blaze brs. N 35½° E, 29.7 ft. Record; N 36½° E.
- A forked Madrone snag with a healed blaze brs. record; S 58° E, 23.1 ft.
- A D. Fir 19 ins. diam. with a healed single blaze brs. record; (per tag) N 11¾° W, 46.2 ft. Presumably marked by BLM in 1985 (per tag).

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- D. Fir 6 ins. diam. brs. S 25¼° W, 16.5 ft.
- D. Fir 10 ins. diam. brs. S 34¼° E, 19.3 ft.

Corner lies northerly approx. 0.9 mile along blocked road from a BLM gate, then approx. 500 ft. west.

October 11, 2010

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 198

V. – 15°50'