

FIRST RE-ESTABLISHMENT

GCDB 340100

Quarter corner common to Section 33, Township 32 South, Range 1 West, and Section 4, Township 33 South, Range 1 West, W.M. $V = 19^\circ$

Found, the single remaining bearing tree recorded by N. Ford in 1855, a black oak, now 12-inch (30 cm) diameter, containing reverse impression of scribed "4S" in opened upper face.

From the preceding evidence, I set a 1x36-inch (2.5x91 cm.) galvanized iron pipe flush with the ground surface, with a 2½-inch (6 cm.) bronze disc marked:

Jackson County 1978
T32S R1W
33
¼S —
4
T33S

From which:

- The above-described original bearing tree bears Record: $N55^\circ E$, 27.06 feet (8.25 m) to (reverse) scribed face.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Douglas fir, 13-inch (33 cm.) diameter bears $S10^\circ W$, 48.49 feet (14.78 m.).
- Black oak, 6-inch (15 cm.) diameter bears $N30^\circ W$, 31.50 feet (9.60 m).

Corner lies on SW slope, about 100 feet (30 m.) West of (8 m.) West of ridge c. South.

February 2, 1978
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT
GCDB 340100

Quarter corner common to Section 33, Township 32 South and Section 4, Township 33 South, Range 1 West, W.M.

Found at the corner position, flush with the ground, the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set on 1st Re-establishment in 1978, marked:

JACKSON COUNTY 1978
T32S R1W
33
¼S —●—
4
T33S

Single remaining original bearing tree recorded by Nathaniel Ford of the GLO in 1855, a b. oak 12 ins. diam. with rotted out faces, brs. N 55° E, 27.4 ft. to center at base. Record; 27.1 ft. to face.

Bearing trees recorded on said 1st Re-establishment found with healed double blazes and measured to center at lower blaze:

- D. fir, now 16 ins. diam. brs. record; S 10° W, 48.5 ft.
- B. oak, now 7 ins. diam. brs. record; N 30° W, 31.5 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- D. fir 9 ins. diam. brs. S 53° E, 32.7 ft.

Corner lies approx. 500 ft. southwesterly down a ridge from bend in spur road.

April 1, 2010
H. Durkee
B. Beeman

Kerry K. Bradshaw
Jackson County Surveyor

P. – 73
V. – 15°30'