

## FIRST RE-ESTABLISHMENT

GCDB 700400

Section corner common to Sections 13 and 24 of Township 32 South, Range 1 West, and Sections 18 and 19 of Township 32 South, Range 1 East, W.M.

Found at corner position exposed 10 ins. the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966 and marked:

T32S  
R1W R1E  
S13 | S18  
—+—  
S24 | S19  
1966

Original bearing trees recorded by Rufus Moore of the GLO in 1883 found and measured to center at base:

- Fir burnt snag brs. N 72° E, 16.0 ft. Record; 17.8 ft. to face.
- Fir sawed burnt stump brs. S 23° W, 20.0 ft. Record; 19.8 ft. to face.
- Fir burnt snag brs. N 53° W, 17.8ft. Record; 18.9 ft. to face.

Bearing trees recorded by the BLM in 1966 found and measured to center at base:

- W. fir burnt snag brs. S 23° E, 58.1 ft. record; 58.7 ft.
- Cedar sawed burnt stump with partially healed blaze brs. record; S 56° W, 42.9 ft.

Set new references: ⅝ in. diam. x 24 ins. rebar with 1½ ins. diam. bronze caps marked

JACKSON COUNTY  
  
SURVEYOR

And exposed 3 ins. near base of burned bearing trees.

- Brs. S 19¾° E, 28.50 ft.
- Brs. S 22¾° W, 17.60 ft.
- Brs. N 53° W, 14.35 ft.
- Brs. N 72½° E, 16.0 ft.

Corner lies approx. 200 ft. southerly from spur road at ridge top.

May 13, 2008

B. Beeman

H. Durkee

Roger R. Roberts

Jackson County Surveyor

P. – 95

V. – 16°25'